Weathertzenton Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO1708Work Order Type: WeatherizationAudit Name: 14014SO1708

CLIENT INFORMATION

Client Name: Address:

Client ID: 14014SO1708 SHELBYVILLE, TN 37160

Alt. Client ID: BEDFORD

AGENCY INFORMATION

Agency: SOUTH CENTRAL HUMAN RESOURCE AGENCY Agency Phone: (931) 433-7182

Address: 1437 WINCHESTER HIGHWAY Fax: (931) 438-0074

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Client Name:
Client ID: 14014SO1708
Alt. Client ID: BEDFORD

Work Order (Bid Form)
Work Order Name: 14014SO1708
Report Run On: 5/21/2010

DOE Weatherization Assistant Version 8.5.0

Page 1 of 7

Measures

Measure 1

Infiltration Redctn

Comment **DO NOT EXCEED 40PA - LOOSE TILE IN LVROOM** / REPAIR CEILING IN LVROOM APPROX. 32 SQ.FT. / CAULK AROUND PLUMBING AND INSIDE WINDOWS / REDUCE INFILTRATION BY 775 CFMS 1. CAULK AND SEAL WINDOWS / REPLACE 2 (ONE WINDOW MISSING STORM HAS BEEN SET BACK IN PLACE, OTHER HAS BROKEN PANE AND ROTTEN FRAME) 2. W/S AND D/S FRONT AND BACK DOORS / FOAM SEAL HOLES AT BOTTOM OF BACK DOOR 3. INSULATE AND SEAL ACCESS / INSTALL 2 LATCHES / INSTALL SCREENS AT BOTH GABLE ENDS 4. INSTALL ACCESS DOOR Estimated Actual									
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Miscellaneous Supplies	Infiltration Reduction	Each	1		7 0 0 0 1			
2	Labor	LABOR	Hour						
C	Other Detail								
				Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:								

Components

Report Run On: 5/21/2010

Inspected

Measure 2 Re	place Htg. System			Componen	ts		ı	Inspected
	ALL VENTER HEATER WI THROUGH CHIMNEY	TH FAN L	ISING	NEW WIRE	FROM E	BOX -		
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Heating Equipment	VENTED HEATER	Each	1					
2 Labor	LABOR	Hour						
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
Field Notes:								
Measure 3 DV	VH Pipe Insulation			Componen				Inspected
Measure 3 DV Comment	·	Unito		Estimated	<u> </u>	Office	Actual	
Measure 3 DV Comment # Material / Labor	WH Pipe Insulation Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty 1	•		Qty		Inspected Total
Measure 3 DV Comment # Material / Labor 1 Insulation	Description / Comment		_	Estimated	<u> </u>	Qty	Actual	
Measure 3 DV Comment # Material / Labor 1 Insulation	Description / Comment DHW Pipe Insulation	Each	1	Estimated	<u> </u>	Qty	Actual	
Measure 3 DV Comment # Material / Labor 1 Insulation 2 Labor	Description / Comment DHW Pipe Insulation	Each	1	Estimated	<u> </u>	Qty	Actual	
Measure 3 DV Comment # Material / Labor 1 Insulation 2 Labor	Description / Comment DHW Pipe Insulation	Each	1	Estimated	<u> </u>	Qty	Actual	
Measure 3 DV Comment # Material / Labor 1 Insulation 2 Labor	Description / Comment DHW Pipe Insulation	Each	1 1	Estimated	<u> </u>		Actual	
Measure 3 DV Comment # Material / Labor 1 Insulation 2 Labor	Description / Comment DHW Pipe Insulation	Each	1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

1	Measure 4 Floo	or Ins. R-19			Componen	ts		ı	nspecte
C	omment								
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	935					
2	Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	935					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
		H Tank Insulation			Componen	ts		,	Inspected
	Measure 5 DW	H Tank Insulation			Componen Estimated			Actual	Inspected
С		H Tank Insulation Description / Comment	Units	Qty	•		Qty		Inspected
<i>C</i>	omment		<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
C #	omment Material / Labor Hot Water	Description / Comment			Estimated		Qty	Actual	
C # 1	Material / Labor Hot Water Equipment	Description / Comment DHW Tank Insulation	Each	1	Estimated		Qty	Actual	
C # 1	Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	1	Estimated		Qty	Actual	
C # 1	Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	1	Estimated		Qty	Actual	
C # 1	Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	1	Estimated			Actual	
c # 1	Material / Labor Hot Water Equipment Labor Other Detail	Description / Comment DHW Tank Insulation	Each	1	Estimated Unit Cost			Actual Unit Cost	
C # 1	Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	1	Estimated Unit Cost			Actual Unit Cost	

Measure 6 Vapor Barrier Needed (Basement/Crawlspace)				Componen	ts		1	Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Basement / crawlspace vapor barrier	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 7 Atti Comment	c Ins. R-19			Componen	4-			
# Material / Labor				Componen				Inspected
# Wateriai / Labor	Description / Comment	Unito		Estimated		<u> </u>	Actual	
1 Insulation	Description / Comment Attic Insulation - Blown Cellulose - R-19	<i>Units</i> SqFt	Qty 935	-		Qty		Total
	Attic Insulation - Blown			Estimated		Qty	Actual	
1 Insulation 2 Labor Other Detail	Attic Insulation - Blown Cellulose - R-19	SqFt		Estimated		Qty	Actual	
2 Labor	Attic Insulation - Blown Cellulose - R-19	SqFt		Estimated		Qty	Actual	
2 Labor	Attic Insulation - Blown Cellulose - R-19	SqFt		Estimated		Qty	Actual	
2 Labor	Attic Insulation - Blown Cellulose - R-19	SqFt Hour	935	Estimated			Actual	
2 Labor	Attic Insulation - Blown Cellulose - R-19	SqFt Hour	935	Estimated Unit Cost			Actual Unit Cost	

					Estimated				
1 Health a	/ Labor				Latimateu			Actual	
1 Health a		Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Items	nd Safety	Metal Flex	Each	1					
2 Labor		Labor	Hour	1					
Other Deta	il] []		
				•] []	Sub Total:	
				weasur	e Sub Total:		•	Sub Total.	
Measure Comment		sureRelief Piping Need	led		Componen			Actual	Inspecte
# Material :	/ Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Unit Cost	Total
1 Health a		•	Each	1		rotar	Qiy		Total
2 Labor		Labor	Hour	1					
Other Deta	il] [
				Measur	e Sub Total:			Sub Total:	
Field Not	es:								

	Measure 10 Smo	ke Detector is Needed			Componen	ts		ı	Inspected
C	comment								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Smoke / Carbon detector	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail			1]		1		
L									
				Measur	e Sub Total:			Sub Total:	
	-	or Barrier Needed ement/Crawlspace)			Componen			ı	Inspected
					Estimated			Actual	
	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Basement / crawlspace vapor barrier	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail				1		7		
L									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
			Work O	rder Gra	and Total:		Gran	d Total:	